


FPR112



VERSION 2101

FPR112 HARDWARE ILLUSTRATION SHEET

A1. M3X5L ROUND INNER HEX SCREW -----[1pcs]

A2. M8X12L HEX HEAD BOLT-----[6pcs]

A3. M10X43L FLAT HEAD SCREW -----[2pcs]

A4. M10X50L FLAT HEAD SCREW -----[2pcs]

A5. M12X90L SOCKET HEAD CAP -----[2pcs]

B1. M8-Ø16 WASHER-----[6pcs]

B2. M12-Ø20 WASHER -----[4pcs]

B3. M12-Ø34 WASHER -----[2pcs]

B4. M8 SPRING WASHER -----[6pcs]

B5. M10 SPRING WASHER -----[4pcs]

B6. M12 SPRING WASHER -----[2pcs]

B7. M10 CAP SLEEVE -----[4pcs]

B8. M12 ROUND LOCK NUT -----[2pcs]

C1. 6MM Allen Wrench -----[1pcs]

C2. 8MM Allen Wrench -----[1pcs]

C3. Screw Driver -----[1pcs]


A1




A2




A3



A4



A5



B1



B2



B3



B4



B5



B6




B7




B8




C1



C2




C3




FPR112 HARDWARE ILLUSTRATION SHEET


a




b




c




d




e




f



g




h




i



Assemble Procedure: a
b
h
A1
A2
B1
B4



Assemble Procedure:



- c
- d
- f
- e
- A3
- A4
- A5
- B2
- B3
- B5
- B6
- B7
- B8

Assemble Procedure: i
g

